



# 1000 Sundura

## 100% Acrylic Exterior Flat Paint

### Product Description

Sundura, a high performance 100% acrylic paint, is appropriate for all exterior walls and trim where durability and beauty are desired. It dries to a matte finish that is flat enough to disguise minor blemishes on the surface being painted, and tough enough to withstand years of exposure to weather. Sundura is available in a nearly limitless array of colors, from the softest, most subtle pastels, to the deepest, richest hues, that will not yellow with age. You can rest assured that your color will last when you use Sundura!

### Performance Features

- Lasting color
- For almost any surface
- Water Cleanup

### Product Specifications

Resin Type:	100% Acrylic
Color Range:	Tintable White, Deep, X-Bases
Finish:	Flat
Drying Time:	To touch: 30-45 minutes To recoat: 2 hours
Practical coverage:	Up to 350 sq ft/gal
Weight per gallon:	11.41 lbs.
Shelf Life:	2 years (unopened container) <90°
Sizes:	Quart, Gallon, 5 Gallon
VOC	< 83 lbs/gal and <98.45 grams/liter
Cleanup:	Water
Solids by weight:	53.56%
Solids by volume:	36.46%

### CAUTIONS

Do not apply when temperature is below 50 degrees F. Do not apply to any exterior surface when rain is expected within 24 hours. Keep from freezing. Keep all unused material in tightly closed containers. Keep away from children. Do not take internally.

### Surface Preparation

#### General

Sundura can be used effectively on stucco, concrete block, drywall, metal, or wood, both exterior and interior. Surfaces to be painted with Sundura must be clean, and free from all dirt, dust, grease, wax, and bleeding stains.

Unpainted: **Concrete** and **stucco** surfaces must be completely cured with a pH no higher than nine. In extremely hot and dry weather it is advisable to dampen new exterior masonry surfaces with clean tap water prior to painting. If there is a question about the condition of stucco or concrete about to be painted, an extra measure of protection is to prime the substrate first with SRK's Stucco Prep. **Wood** surfaces can be primed with a coat of Sundura. However, if there is a possibility of tannin staining, use a primer with stain-blocking capabilities.

Repaint: all surfaces to be painted must be clean and free of all dirt, dust, loose or flaking paint, grease, or any other foreign matter. Remove all loose, scaling paint with a wire brush, a sandblaster, or a water blaster. Chalky surfaces must be thoroughly cleaned by scrubbing with warm soapy water, and be rinsed well.

#### Application

Sundura may be applied with a brush, roller, or airless spray equipment. Clean equipment with water immediately after use.

#### Thinning

Up to 10% of clean tap water may be used to thin to the desired working consistency.

**WARNING:** If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to [www.epa.gov/lead](http://www.epa.gov/lead).