



# 1400 Sunshield

## 100% Acrylic Exterior Flat Paint

### Product Description

Sunshield, a high solids 100% acrylic latex flat paint, contains a water repellent silicone resin that becomes an integral part of the dried paint film. This resin will not leach from the film even after years of exposure to the elements, allowing the film to resist alkalinity and efflorescence problems on stucco substrates, and woodgrain cracks on wood substrates. Sunshield provides adequate hiding with just one coat, and is readily re-paintable. Choose Sunshield for maximum water repellency and lasting beauty!

### Performance Features

- Water-repellent
- One coat
- Water Cleanup

### Product Specifications

Resin Type:	100% Acrylic
Color Range:	Tintable White, Deep, X-Bases
Finish:	Flat
Drying Time:	To touch: 15-30 minutes To recoat: 2 hours
Practical coverage:	Up to 300 sq ft/gal
Weight per gallon:	11.45 lbs.
Shelf Life:	2 years (unopened container) <90°
Sizes:	Gallon, 5 Gallon
VOC	<.35 lbs/gal and <41.8 grams/liter
Cleanup:	Water
Solids by weight:	52.48%
Solids by volume:	34.48%

### CAUTIONS

Do not apply when temperature is below 55 degrees F. Do not apply to any exterior surface when rain is expected within 24 hours. Keep from freezing. Keep all unused material in tightly closed containers. Keep away from children. Do not take internally.

### Surface Preparation

#### General

Sunshield can be used effectively on exterior stucco, concrete, block, or wood. Surfaces to be painted with Sunshield must be clean, and free from all dirt, dust, grease, wax, and bleeding stains.

New: **Concrete** and **stucco** surfaces must be completely cured with a pH no higher than 10. A prime coat of SRK Stucco Cure is recommended over raw stucco, or Stucco Prep over previously-painted stucco. When Sunshield is used properly in conjunction with SRK Stucco Cure or Stucco Prep, concrete and stucco are rendered impenetrable to water. On stucco that is showing multiple hairline cracks, a coat of SRK Stucco Fix is recommended. **Wood** surfaces do not require a primer. However, if there is a possibility of tannin staining, use a primer with stain blockers.

Repaint: All surfaces to be painted must be clean and free of all dirt, dust, loose or flaking paint, grease, or any other foreign matter. Remove all loose, scaling paint with a wire brush, a sandblaster, or a water blaster. Chalky surfaces must be thoroughly cleaned by scrubbing with warm soapy water, and be rinsed

#### Application

Sunshield may be applied with a brush, roller, or airless spray equipment. Clean equipment with water immediately after use.

#### Thinning

Up to 10% of clean tap water may be used to thin to the desired working consistency.

WARNING: If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to [www.epa.gov/lead](http://www.epa.gov/lead).